DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-010622 Address: 333 Burma Road **Date Inspected:** 30-Nov-2009

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 700 **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Chen Ying Xin No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** Tower

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 10

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

NSD1-TL5-3C-F-7A/B (NORTH TOWER LIFT 5 SKIN "E")

SSD1-TL5-1C-F-8A/B (SOUTH TOWER LIFT 5 SKIN "E")

SSD1-TL5-1E-F-14A/B (SOUTH TOWER LIFT 5 SKIN "A")

ED1-A5001-30-1A/B (STRUT ANGLE)

SSD1-SPSA4-22-1A/B, 2A/B (SOUTH TOWER INTERIOR SPLICE PLATE OF SKIN "E")

This Quality Assurance (QA) Inspector observed the following work in progress:

Bay 10

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SMAW welding of weld joint 29 located on ND1-A6002-11.

Welder is identified as 053050. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-2113.

SMAW welding of weld joint 54 located on ED1-STSA3-2-89M-2.

Welder is identified as 067904. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-4113-1.

FCAW welding of weld joint 2A located on NSD1-SPSA4-20.

Welder is identified as 040343. ZPMC QC is identified as Mr. Deng Zhi Bing.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-Tc-U5-F.

FCAW welding of weld joint 1A located on SSD1-SPSA4-18.

Welder is identified as 040533. ZPMC QC is identified as Mr. Deng Zhi Bing.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-Tc-U5-F.

SMAW welding of weld joint 25B located on ND1-STSA3-1-89M-1.

Welder is identified as 040333. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-3212-Tc-U5b-1.

SOUTH TOWER LIFT 5 SKIN "D"

SAW welding of weld joint 13B located on SSD1-TL5-1E-F.

Welder is identified as 207745. ZPMC QC is identified as Jiang La Mei.

The welding variables recorded by QC appeared to comply with WPS-B-T-3221-B-U3c-S-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
Reviewed By:	Clifford, William	QA Reviewer